

OFFICIAL PHOTOGRAPH

WATER QUALITY DIVISION/WYOMING DEPARTMENT OF ENVIRONMENTAL QUALITY UNDERGROUND INJECTION CONTROL PROGRAM

Photograph Number	WYS-029-00219 IMG_7128.jpg
Subject	Complaint inspection of leaking septic system
Location	Intersection of Saddle Hill Road and Shirley Road, just north of Meeteetse, WY
County	Park
Date	12 July 2013
Approximate Time	11:10
Photographer	Kathy Shreve
Witness	Jim O'Connor
View Direction	North
Weather	Sunny, cloudy, warm approx.. 85 F
Path	
Comments	Leachfield. Note lush vegetation and riser pipe. Subdivision is immediately to the east of the leachfield, just across Saddle Hill Road.



OFFICIAL PHOTOGRAPH

WATER QUALITY DIVISION/WYOMING DEPARTMENT OF ENVIRONMENTAL QUALITY
UNDERGROUND INJECTION CONTROL PROGRAM

Photograph Number	WYS-029-00219 IMG_7129.jpg
Subject	Complaint inspection of leaking septic system
Location	Intersection of Saddle Hill Road and Shirley Road, just north of Meeteetse, WY
County	Park
Date	12 July 2013
Approximate Time	11:10
Photographer	Kathy Shreve
Witness	Jim O'Connor
View Direction	North
Weather	Sunny, cloudy, warm approx.. 85 F
Path	
Comments	Close-up of lush vegetation growing on leaking leachfield.



OFFICIAL PHOTOGRAPH

WATER QUALITY DIVISION/WYOMING DEPARTMENT OF ENVIRONMENTAL QUALITY

UNDERGROUND INJECTION CONTROL PROGRAM

Photograph Number	WYS-029-00219 IMG_7131.jpg
Subject	Complaint inspection of leaking septic system
Location	Intersection of Saddle Hill Road and Shirley Road, just north of Meeteetse, WY
County	Park
Date	12 July 2013
Approximate Time	11:12
Photographer	Kathy Shreve
Witness	Jim O'Connor
View Direction	NA
Weather	Sunny, cloudy, warm approx.. 85 F
Path	
Comments	Water surfacing from leaking septic system on north side of leachfield. It was hard to get an estimate of the volume of water leaking to the surface due to the large amount of tall grass growing on the leachfield (2-3 feet tall in areas). Vegetation in the surrounding areas was short, dry and brown due to drought and cattle grazing.



OFFICIAL PHOTOGRAPH

WATER QUALITY DIVISION/WYOMING DEPARTMENT OF ENVIRONMENTAL QUALITY UNDERGROUND INJECTION CONTROL PROGRAM

Photograph Number	WYS-029-00219 IMG_7132.jpg
Subject	Complaint inspection of leaking septic system
Location	Intersection of Saddle Hill Road and Shirley Road, just north of Meeteetse, WY
County	Park
Date	12 July 2013
Approximate Time	11:13
Photographer	Kathy Shreve
Witness	Jim O'Connor
View Direction	North
Weather	Sunny, cloudy, warm approx.. 85 F
Path	
Comments	Green lush vegetation (with saturated soil underneath) from the north edge of the leachfield, going north to the adjacent draw.



OFFICIAL PHOTOGRAPH

WATER QUALITY DIVISION/WYOMING DEPARTMENT OF ENVIRONMENTAL QUALITY UNDERGROUND INJECTION CONTROL PROGRAM

Photograph Number	WYS-029-00219 IMG_7137.jpg
Subject	Complaint inspection of leaking septic system
Location	Intersection of Saddle Hill Road and Shirley Road, just north of Meeteetse, WY
County	Park
Date	12 July 2013
Approximate Time	11:23
Photographer	Kathy Shreve
Witness	Jim O'Connor
View Direction	East
Weather	Sunny, cloudy, warm approx.. 85 F
Path	
Comments	Lush vegetation (with saturated soil underneath) at culvert crossing Saddle Hill Road (I'm standing on the culvert).



OFFICIAL PHOTOGRAPH

WATER QUALITY DIVISION/WYOMING DEPARTMENT OF ENVIRONMENTAL QUALITY UNDERGROUND INJECTION CONTROL PROGRAM

Photograph Number	WYS-029-00219 IMG_7138.jpg
Subject	Complaint inspection of leaking septic system
Location	Intersection of Saddle Hill Road and Shirley Road, just north of Meeteetse, WY
County	Park
Date	12 July 2013
Approximate Time	11:24
Photographer	Kathy Shreve
Witness	Jim O'Connor
View Direction	East
Weather	Sunny, cloudy, warm approx.. 85 F
Path	
Comments	Different (further) view of culvert crossing Saddle Hill Road with lush vegetation (I'm standing on culvert).



OFFICIAL PHOTOGRAPH

WATER QUALITY DIVISION/WYOMING DEPARTMENT OF ENVIRONMENTAL QUALITY UNDERGROUND INJECTION CONTROL PROGRAM

Photograph Number	WYS-029-00219 IMG_7143.jpg
Subject	Complaint inspection of leaking septic system
Location	Intersection of Saddle Hill Road and Shirley Road, just north of Meeteetse, WY
County	Park
Date	12 July 2013
Approximate Time	11:27
Photographer	Kathy Shreve
Witness	Jim O'Connor
View Direction	West
Weather	Sunny, cloudy, warm approx.. 85 F
Path	
Comments	Lush vegetation (with saturated soil underneath) on East side of Saddle Hill Road (side of Saddle Hill Road opposite the leachfield)



OFFICIAL PHOTOGRAPH

WATER QUALITY DIVISION/WYOMING DEPARTMENT OF ENVIRONMENTAL QUALITY UNDERGROUND INJECTION CONTROL PROGRAM

Photograph Number	WYS-029-00219 IMG_7144.jpg
Subject	Complaint inspection of leaking septic system
Location	Intersection of Saddle Hill Road and Shirley Road, just north of Meeteetse, WY
County	Park
Date	12 July 2013
Approximate Time	11:29
Photographer	Kathy Shreve
Witness	Jim O'Connor
View Direction	East
Weather	Sunny, cloudy, warm approx.. 85 F
Path	
Comments	Culvert crossing HWY 120 from Saddle Hill Road. Note lush vegetation, soils in the vegetated area were saturated.



OFFICIAL PHOTOGRAPH

WATER QUALITY DIVISION/WYOMING DEPARTMENT OF ENVIRONMENTAL QUALITY UNDERGROUND INJECTION CONTROL PROGRAM

Photograph Number	WYS-029-00219 IMG_7145.jpg
Subject	Complaint inspection of leaking septic system
Location	Intersection of Saddle Hill Road and Shirley Road, just north of Meeteetse, WY
County	Park
Date	12 July 2013
Approximate Time	11:29
Photographer	Kathy Shreve
Witness	Jim O'Connor
View Direction	East
Weather	Sunny, cloudy, warm approx.. 85 F
Path	
Comments	Water oozing from saturated soils into culvert crossing Hwy 120. Sample collected in this culvert for ammonia and nitrate-nitrite.



OFFICIAL PHOTOGRAPH

WATER QUALITY DIVISION/WYOMING DEPARTMENT OF ENVIRONMENTAL QUALITY UNDERGROUND INJECTION CONTROL PROGRAM

Photograph Number	WYS-029-00219 IMG_7147.jpg
Subject	Complaint inspection of leaking septic system
Location	Intersection of Saddle Hill Road and Shirley Road, just north of Meeteetse, WY
County	Park
Date	12 July 2013
Approximate Time	11:45
Photographer	Kathy Shreve
Witness	Jim O'Connor
View Direction	West
Weather	Sunny, cloudy, warm approx.. 85 F
Path	
Comments	Culvert on east (opposite side of hwy 120 from Crossed Arrows Subdivision) I'm pointing to the culvert. Note the very lush vegetation. Soils saturated underneath the tall vegetation. Subdivision located in background, over the hill. Access road to subdivision behind parked SUV.



OFFICIAL PHOTOGRAPH

WATER QUALITY DIVISION/WYOMING DEPARTMENT OF ENVIRONMENTAL QUALITY UNDERGROUND INJECTION CONTROL PROGRAM

Photograph Number	WYS-029-00219 IMG_7148.jpg
Subject	Complaint inspection of leaking septic system
Location	Intersection of Saddle Hill Road and Shirley Road, just north of Meeteetse, WY
County	Park
Date	12 July 2013
Approximate Time	11:24
Photographer	Kathy Shreve
Witness	Jim O'Connor
View Direction	North
Weather	Sunny, cloudy, warm approx.. 85 F
Path	
Comments	Irrigation return flow ditch located immediately to the east of fence in foreground of previous photograph.

