



Jim Ruby <jim.ruby@wyo.gov>

Technically inadequate permit (WDEQ-LQD Mining Permit 267C – WSL04 – TFN #6 1/197)

1 message

Ronald Ericsson <ericsson@childselect.com>

Fri, Jul 20, 2018 at 3:11 PM

To: "kyle.wendtland@wyo.gov" <kyle.wendtland@wyo.gov>

Cc: "todd.parfitt@wyo.gov" <todd.parfitt@wyo.gov>, "josh.malmberg@wyo.gov" <josh.malmberg@wyo.gov>, "jim.ruby@wyo.gov" <jim.ruby@wyo.gov>, "kari.gray@wyo.gov" <kari.gray@wyo.gov>, "SecofState@wyo.gov" <SecofState@wyo.gov>, "bridget.hill1@wyo.gov" <bridget.hill1@wyo.gov>, "Ogden.Driskill@wyoleg.gov" <Ogden.Driskill@wyoleg.gov>, Lucy Pauley <lucy.pauley@wyo.gov>, "Lyndon.Bucher@mineralstech.com" <Lyndon.Bucher@mineralstech.com>, "don.eisenhour@colloid.com" <don.eisenhour@colloid.com>, "mark.wardell@colloid.com" <mark.wardell@colloid.com>, "sara.vetter@colloid.com" <sara.vetter@colloid.com>, "rodney.raber@colloid.com" <rodney.raber@colloid.com>, "rodney.wheaton@mineralstech.com" <rodney.wheaton@mineralstech.com>, "jason.schneider@mineralstech.com" <jason.schneider@mineralstech.com>, Melody Smith <melody.smith@colloid.com>, Joel Severin <joel.severin@halliburton.com>, Tyler Tetrault <tyler.tetrault@halliburton.com>, "Warren.Scott@halliburton.com" <Warren.Scott@halliburton.com>, Roxie Dacar <roxiedacar@gmail.com>, Jim Dacar <jimdacar@gmail.com>, Levi Dacar <levi.dacar@wyo.gov>, "dacar9625@gmail.com" <dacar9625@gmail.com>, "mvictoria.ericsson@gmail.com" <mvictoria.ericsson@gmail.com>, Spencer Ericsson <ericsson1337@yahoo.com>, "gargawill@gmail.com" <gargawill@gmail.com>, Julie Anderson <bakergirlhomade@aol.com>, Jean Ericsson <gam4@rangeweb.net>, "rolandericsson@cox.net" <rolandericsson@cox.net>, Beverly Keegan <bkeegan@vcn.com>, Kim Hayworth <khayworth@midco.net>, "treasurer@wyo.gov" <treasurer@wyo.gov>, "askthesuperintendent@wyo.gov" <askthesuperintendent@wyo.gov>, "SAOAdmin@wyo.gov" <SAOAdmin@wyo.gov>, Jennifer Hartman <jennifer.hartman@halliburton.com>

July 20, 2018

Kyle Wendtland
 Administrator
 Department of Environmental Quality
 200 West 17th Street
 Cheyenne, WY 82002

RE: Technically inadequate permit (WDEQ-LQD Mining Permit 267C – Wyoming State Mineral Lease 42804 – TFN #6 1/197)

Dear Mr. Kyle J. Wendtland:

The WDEQ-LQD Mining Permit 267C – Wyoming State Mineral Lease 42804 – TFN #6 1/197) is technically inadequate for the following reasons:

Section 2.11.8.6 Post-mining Tree Restoration states “The permittee will not replant the destroyed trees unless the surface owner specifically requests restoration in writing. If a surface owner wants trees replanted, the permittee will include specific Reclamation Plan text which details the replanting methods and locations.”

We have requested in writing (see attached certified letter to Bentonite Performance Minerals (BPM) 11/13/2007) that all of the 10,936 trees that will be disturbed by mining to be replanted.

Section 2.11.41-6 Revegetation & Seed – The latest version sent by BPM eliminated the statement “However, the landowner, Lonesome County LC, has requested that no trees be replaced in the reclamation”. This was incorrect landownership. The landowners are members of the 2U Ranch, LLC not Lonesome County LC and we want tree reclamation. We would like the permit to be amended to reflect the true landowners and to state that we want tree reclamation.

Section 2.11.41 Wyoming State Lease 42804 (WSL04) Amendment Reclamation Plan does not include specific Reclamation Plan text which details the replanting methods and locations as required by Section 2.11.8.6 Post-mining Tree Restoration of the permit. We would like the permit to be amended to provide the required information on the replanting of trees.

Sincerely,

Ronald J. Ericsson, PhD
Scott A. Ericsson, PhD
Roland S. Ericsson, Esquire



Certified letter - tree reclamation.pdf

2535K