



Department of Environmental Quality

To protect, conserve and enhance the quality of Wyoming's environment for the benefit of current and future generations.



Matthew H. Mead, Governor

John Corra, Director

July 23, 2012

CERTIFIED

Stephen & Audrey Smith
 Crossed Arrows Subdivision
 P. O. Box 279
 Meeteetse, WY 82433

RE: SURFACING SEPTIC SYSTEM EFFLUENT, SUBMISSION OF UNDERGROUND INJECTION CONTROL PERMIT FOR CROSSED ARROWS SUBDIVISION'S SEPTIC SYSTEM

Dear Mr. & Mrs. Smith,

The Underground Injection Control Program of the Wyoming Department of Environmental Quality, Water Quality Division (UIC Program), has been informed from multiple sources that the septic system for this facility serves at least 12 households. Average water disposal per household is generally accepted to be 350 gallons per day, which means that the septic system for the Crossed Arrows Subdivision accepts, at a minimum, 4,200 gallons per day of domestic waste. According to *Wyoming Water Quality Rules and Regulations, Chapter 16, Appendix A*, this facility qualifies as a 5E3 Domestic Subsurface Fluid Distribution System. The UIC Program hereby requires the Crossed Arrows Subdivision to initiate permit coverage through the UIC Program by completing and submitting a technically adequate individual permit application. If you would like to download an electronic version of this application, you can do so at the following website: <http://deq.state.wy.us/wqd/groundwater/uicprogram/index.asp>, once you reach this webpage, please scroll down the page to the "Class V Well Permit Application" link, clicking on this link will take you to the download screen. If you need assistance with this application, please contact any of the following:

Kathy Shreve
 307-777-6682
kathy.shreve@wyo.gov

Carol McAdams
 307-777-2960
carol.mcadams@wyo.gov

Nicole Twing
 307-777-8275
nicole.twing@wyo.gov

Please note that operating a Class V injection well (which includes septic systems that accept more than 2,000 gallons per day of domestic waste) is a violation of *Wyoming Water Quality Rules and Regulations*. Violation of these regulations can incur enforcement actions, which can include fines and penalties.

The UIC Program has been notified by multiple sources that the septic system (leachfield) for the Crossed Arrows subdivision has failed, and that sewage is flowing onto the surface at this




facility. Please note that “the operation of any Class V septic system with liquid waste visible on the surface shall be considered a failure of the system and a violation of these regulations.” according to *Wyoming Water Quality Rules and Regulations, Chapter 16, Section 9.j*. In order to rectify this situation and avoid further enforcement actions, Crossed Arrows Subdivision must accomplish the following:

1. Immediately cease discharge of domestic waste into the failed leachfield.
2. Discharge into this facility’s septic tank may continue, provided that the septic tank is pumped as often as necessary to prevent the domestic sewage from overflowing the tank. In addition, the domestic sewage pumped from this facility’s tank must be disposed of in an approved facility.
3. Remediate/replace the failed leachfield in accordance with *Wyoming Water Quality Rules and Regulations, Chapter 11, Section D*. According to information on file with various other agencies, it appears that this facility’s leachfield has had multiple failures since 1991, strongly indicating the need for leachfield replacement, likely by a different system than exists now.
4. Notify the Region 8 office of the EPA regarding this facility’s leachfield failure, and conduct immediate water supply well testing to eliminate the possibility that the water supply for the Crossed Arrows subdivision has been contaminated.

Please remain in touch with the UIC Program regarding the accomplishment of each of the steps outlined below. Please note that failure to complete these steps in a timely manner may result in enforcement actions being taken against this facility.

If you have any questions, please contact me at the phone number or e-mail given above.

Sincerely,



Kathy Shreve
Environmental Program Principal
Wyoming Department of Environmental Quality
Water Quality Division
Underground Injection Control Program

KS/rm/12-0661



Department of Environmental Quality

To protect, conserve and enhance the quality of Wyoming's environment for the benefit of current and future generations.



Matthew H. Mead, Governor

John Corra, Director

July 20, 2012

CERTIFIED

Byran Anderson
Crossed Arrows Subdivision
P. O. Box 254
Meeteetse, WY 82433

RE: SURFACING SEPTIC SYSTEM EFFLUENT, SUBMISSION OF UNDERGROUND INJECTION CONTROL PERMIT FOR CROSSED ARROWS SUBDIVISION'S SEPTIC SYSTEM

Dear Mr. Anderson,

The Underground Injection Control Program of the Wyoming Department of Environmental Quality, Water Quality Division (UIC Program), has been informed from multiple sources that the septic system for this facility serves at least 12 households. Average water disposal per household is generally accepted to be 350 gallons per day, which means that the septic system for the Crossed Arrows Subdivision accepts, at a minimum, 4,200 gallons per day of domestic waste. According to *Wyoming Water Quality Rules and Regulations, Chapter 16, Appendix A*, this facility qualifies as a 5E3 Domestic Subsurface Fluid Distribution System. The UIC Program hereby requires the Crossed Arrows Subdivision to initiate permit coverage through the UIC Program by completing and submitting a technically adequate individual permit application. If you would like to download an electronic version of this application, you can do so at the following website: <http://deq.state.wy.us/wqd/groundwater/uicprogram/index.asp>, once you reach this webpage, please scroll down the page to the "Class V Well Permit Application" link, clicking on this link will take you to the download screen. If you need assistance with this application, please contact any of the following:

Kathy Shreve
307-777-6682
kathy.shreve@wyo.gov

Carol McAdams
307-777-2960
carol.mcadams@wyo.gov

Nicole Twing
307-777-8275
nicole.twing@wyo.gov

Please note that operating a Class V injection well (which includes septic systems that accept more than 2,000 gallons per day of domestic waste) is a violation of *Wyoming Water Quality Rules and Regulations*. Violation of these regulations can incur enforcement actions, which can include fines and penalties.

The UIC Program has been notified by multiple sources that the septic system (leachfield) for the Crossed Arrows subdivision has failed, and that sewage is flowing onto the surface at this




facility. Please note that “the operation of any Class V septic system with liquid waste visible on the surface shall be considered a failure of the system and a violation of these regulations.” according to *Wyoming Water Quality Rules and Regulations, Chapter 16, Section 9.j*. In order to rectify this situation and avoid further enforcement actions, Crossed Arrows Subdivision must accomplish the following:

1. Immediately cease discharge of domestic waste into the failed leachfield.
2. Discharge into this facility’s septic tank may continue, provided that the septic tank is pumped as often as necessary to prevent the domestic sewage from overflowing the tank. In addition, the domestic sewage pumped from this facility’s tank must be disposed of in an approved facility.
3. Remediate/replace the failed leachfield in accordance with *Wyoming Water Quality Rules and Regulations, Chapter 11, Section D*. According to information on file with various other agencies, it appears that this facility’s leachfield has had multiple failures since 1991, strongly indicating the need for leachfield replacement, likely by a different system than exists now.
4. Notify the Region 8 office of the EPA regarding this facility’s leachfield failure, and conduct immediate water supply well testing to eliminate the possibility that the water supply for the Crossed Arrows subdivision has been contaminated.

Please remain in touch with the UIC Program regarding the accomplishment of each of the steps outlined below. Please note that failure to complete these steps in a timely manner may result in enforcement actions being taken against this facility.

If you have any questions, please contact me at the phone number or e-mail given above.

Sincerely,



Kathy Shreve
Environmental Program Principal
Wyoming Department of Environmental Quality
Water Quality Division
Underground Injection Control Program

KS/rm/12-0660



Department of Environmental Quality

To protect, conserve and enhance the quality of Wyoming's environment for the benefit of current and future generations.



Matthew H. Mead, Governor

John Corra, Director

July 20, 2012

CERTIFIED

Glen and Terry Moore
Crossed Arrows Subdivision
P. O. Box 254
Meeteetse, WY 82433

RE: SURFACING SEPTIC SYSTEM EFFLUENT, SUBMISSION OF UNDERGROUND INJECTION CONTROL PERMIT FOR CROSSED ARROWS SUBDIVISION'S SEPTIC SYSTEM

Dear Mr. and Mrs. Moore,

The Underground Injection Control Program of the Wyoming Department of Environmental Quality, Water Quality Division (UIC Program), has been informed from multiple sources that the septic system for this facility serves at least 12 households. Average water disposal per household is generally accepted to be 350 gallons per day, which means that the septic system for the Crossed Arrows Subdivision accepts, at a minimum, 4,200 gallons per day of domestic waste. According to *Wyoming Water Quality Rules and Regulations, Chapter 16, Appendix A*, this facility qualifies as a 5E3 Domestic Subsurface Fluid Distribution System. The UIC Program hereby requires the Crossed Arrows Subdivision to initiate permit coverage through the UIC Program by completing and submitting a technically adequate individual permit application. If you would like to download an electronic version of this application, you can do so at the following website: <http://deq.state.wy.us/wqd/groundwater/uicprogram/index.asp>, once you reach this webpage, please scroll down the page to the "Class V Well Permit Application" link, clicking on this link will take you to the download screen. If you need assistance with this application, please contact any of the following:

Kathy Shreve
307-777-6682
kathy.shreve@wyo.gov

Carol McAdams
307-777-2960
carol.mcadams@wyo.gov

Nicole Twing
307-777-8275
nicole.twing@wyo.gov

Please note that operating a Class V injection well (which includes septic systems that accept more than 2,000 gallons per day of domestic waste) is a violation of *Wyoming Water Quality Rules and Regulations*. Violation of these regulations can incur enforcement actions, which can include fines and penalties.




The UIC Program has been notified by multiple sources that the septic system (leachfield) for the Crossed Arrows subdivision has failed, and that sewage is flowing onto the surface at this facility. Please note that "the operation of any Class V septic system with liquid waste visible on the surface shall be considered a failure of the system and a violation of these regulations." according to *Wyoming Water Quality Rules and Regulations, Chapter 16, Section 9.j*. In order to rectify this situation and avoid further enforcement actions, Crossed Arrows Subdivision must accomplish the following:

1. Immediately cease discharge of domestic waste into the failed leachfield.
2. Discharge into this facility's septic tank may continue, provided that the septic tank is pumped as often as necessary to prevent the domestic sewage from overflowing the tank. In addition, the domestic sewage pumped from this facility's tank must be disposed of in an approved facility.
3. Remediate/replace the failed leachfield in accordance with *Wyoming Water Quality Rules and Regulations, Chapter 11, Section D*. According to information on file with various other agencies, it appears that this facility's leachfield has had multiple failures since 1991, strongly indicating the need for leachfield replacement, likely by a different system than exists now.
4. Notify the Region 8 office of the EPA regarding this facility's leachfield failure, and conduct immediate water supply well testing to eliminate the possibility that the water supply for the Crossed Arrows subdivision has been contaminated.

Please remain in touch with the UIC Program regarding the accomplishment of each of the steps outlined below. Please note that failure to complete these steps in a timely manner may result in enforcement actions being taken against this facility.

If you have any questions, please contact me at the phone number or e-mail given above.

Sincerely,



Kathy Shreve
Environmental Program Principal
Wyoming Department of Environmental Quality
Water Quality Division
Underground Injection Control Program

KS/rm/12-0659



Department of Environmental Quality

To protect, conserve and enhance the quality of Wyoming's environment for the benefit of current and future generations.



Matthew H. Mead, Governor

John Corra, Director

July 23, 2012

CERTIFIED

Randall & Teresa Faugh
Crossed Arrows Subdivision
P. O. Box 135
Meeteetse, WY 82433

RE: SURFACING SEPTIC SYSTEM EFFLUENT, SUBMISSION OF UNDERGROUND INJECTION CONTROL PERMIT FOR CROSSED ARROWS SUBDIVISION'S SEPTIC SYSTEM

Dear Mr. & Mrs. Faugh,

The Underground Injection Control Program of the Wyoming Department of Environmental Quality, Water Quality Division (UIC Program), has been informed from multiple sources that the septic system for this facility serves at least 12 households. Average water disposal per household is generally accepted to be 350 gallons per day, which means that the septic system for the Crossed Arrows Subdivision accepts, at a minimum, 4,200 gallons per day of domestic waste. According to *Wyoming Water Quality Rules and Regulations, Chapter 16, Appendix A*, this facility qualifies as a 5E3 Domestic Subsurface Fluid Distribution System. The UIC Program hereby requires the Crossed Arrows Subdivision to initiate permit coverage through the UIC Program by completing and submitting a technically adequate individual permit application. If you would like to download an electronic version of this application, you can do so at the following website: <http://deq.state.wy.us/wqd/groundwater/uicprogram/index.asp>, once you reach this webpage, please scroll down the page to the "Class V Well Permit Application" link, clicking on this link will take you to the download screen. If you need assistance with this application, please contact any of the following:

Kathy Shreve
307-777-6682
kathy.shreve@wyo.gov

Carol McAdams
307-777-2960
carol.mcadams@wyo.gov

Nicole Twing
307-777-8275
nicole.twing@wyo.gov

Please note that operating a Class V injection well (which includes septic systems that accept more than 2,000 gallons per day of domestic waste) is a violation of *Wyoming Water Quality Rules and Regulations*. Violation of these regulations can incur enforcement actions, which can include fines and penalties.

The UIC Program has been notified by multiple sources that the septic system (leachfield) for the Crossed Arrows subdivision has failed, and that sewage is flowing onto the surface at this




facility. Please note that “the operation of any Class V septic system with liquid waste visible on the surface shall be considered a failure of the system and a violation of these regulations.” according to *Wyoming Water Quality Rules and Regulations, Chapter 16, Section 9.j*. In order to rectify this situation and avoid further enforcement actions, Crossed Arrows Subdivision must accomplish the following:

1. Immediately cease discharge of domestic waste into the failed leachfield.
2. Discharge into this facility’s septic tank may continue, provided that the septic tank is pumped as often as necessary to prevent the domestic sewage from overflowing the tank. In addition, the domestic sewage pumped from this facility’s tank must be disposed of in an approved facility.
3. Remediate/replace the failed leachfield in accordance with *Wyoming Water Quality Rules and Regulations, Chapter 11, Section D*. According to information on file with various other agencies, it appears that this facility’s leachfield has had multiple failures since 1991, strongly indicating the need for leachfield replacement, likely by a different system than exists now.
4. Notify the Region 8 office of the EPA regarding this facility’s leachfield failure, and conduct immediate water supply well testing to eliminate the possibility that the water supply for the Crossed Arrows subdivision has been contaminated.

Please remain in touch with the UIC Program regarding the accomplishment of each of the steps outlined below. Please note that failure to complete these steps in a timely manner may result in enforcement actions being taken against this facility.

If you have any questions, please contact me at the phone number or e-mail given above.

Sincerely,




Kathy Shreve
Environmental Program Principal
Wyoming Department of Environmental Quality
Water Quality Division
Underground Injection Control Program

KS/rm/12-0662



Department of Environmental Quality

To protect, conserve and enhance the quality of Wyoming's environment for the benefit of current and future generations.



Matthew H. Mead, Governor

John Corra, Director

July 23, 2012

CERTIFIED

Brenda Edwards
Crossed Arrows Subdivision
342 W. Liberty St.
Weiser, ID 83672

RE: SURFACING SEPTIC SYSTEM EFFLUENT, SUBMISSION OF UNDERGROUND INJECTION CONTROL PERMIT FOR CROSSED ARROWS SUBDIVISION'S SEPTIC SYSTEM

Dear Ms Edwards,

The Underground Injection Control Program of the Wyoming Department of Environmental Quality, Water Quality Division (UIC Program), has been informed from multiple sources that the septic system for this facility serves at least 12 households. Average water disposal per household is generally accepted to be 350 gallons per day, which means that the septic system for the Crossed Arrows Subdivision accepts, at a minimum, 4,200 gallons per day of domestic waste. According to *Wyoming Water Quality Rules and Regulations, Chapter 16, Appendix A*, this facility qualifies as a 5E3 Domestic Subsurface Fluid Distribution System. The UIC Program hereby requires the Crossed Arrows Subdivision to initiate permit coverage through the UIC Program by completing and submitting a technically adequate individual permit application. If you would like to download an electronic version of this application, you can do so at the following website: <http://deq.state.wy.us/wqd/groundwater/uicprogram/index.asp>, once you reach this webpage, please scroll down the page to the "Class V Well Permit Application" link, clicking on this link will take you to the download screen. If you need assistance with this application, please contact any of the following:

Kathy Shreve
307-777-6682
kathy.shreve@wyo.gov

Carol McAdams
307-777-2960
carol.mcadams@wyo.gov

Nicole Twing
307-777-8275
nicole.twing@wyo.gov

Please note that operating a Class V injection well (which includes septic systems that accept more than 2,000 gallons per day of domestic waste) is a violation of *Wyoming Water Quality Rules and Regulations*. Violation of these regulations can incur enforcement actions, which can include fines and penalties.



The UIC Program has been notified by multiple sources that the septic system (leachfield) for the Crossed Arrows subdivision has failed, and that sewage is flowing onto the surface at this facility. Please note that "the operation of any Class V septic system with liquid waste visible on the surface shall be considered a failure of the system and a violation of these regulations." according to *Wyoming Water Quality Rules and Regulations, Chapter 16, Section 9.j*. In order to rectify this situation and avoid further enforcement actions, Crossed Arrows Subdivision must accomplish the following:

1. Immediately cease discharge of domestic waste into the failed leachfield.
2. Discharge into this facility's septic tank may continue, provided that the septic tank is pumped as often as necessary to prevent the domestic sewage from overflowing the tank. In addition, the domestic sewage pumped from this facility's tank must be disposed of in an approved facility.
3. Remediate/replace the failed leachfield in accordance with *Wyoming Water Quality Rules and Regulations, Chapter 11, Section D*. According to information on file with various other agencies, it appears that this facility's leachfield has had multiple failures since 1991, strongly indicating the need for leachfield replacement, likely by a different system than exists now.
4. Notify the Region 8 office of the EPA regarding this facility's leachfield failure, and conduct immediate water supply well testing to eliminate the possibility that the water supply for the Crossed Arrows subdivision has been contaminated.

Please remain in touch with the UIC Program regarding the accomplishment of each of the steps outlined below. Please note that failure to complete these steps in a timely manner may result in enforcement actions being taken against this facility.

If you have any questions, please contact me at the phone number or e-mail given above.

Sincerely,



Kathy Shreve


Environmental Program Principal
Wyoming Department of Environmental Quality
Water Quality Division
Underground Injection Control Program

KS/rm/12-0663



Department of Environmental Quality

To protect, conserve and enhance the quality of Wyoming's environment for the benefit of current and future generations.



Matthew H. Mead, Governor

John Corra, Director

July 23, 2012

CERTIFIED

Anthony Graves
Crossed Arrows Subdivision
P.O. Box 357
Meeteetse, WY 82433

RE: SURFACING SEPTIC SYSTEM EFFLUENT, SUBMISSION OF UNDERGROUND INJECTION CONTROL PERMIT FOR CROSSED ARROWS SUBDIVISION'S SEPTIC SYSTEM

Dear Mr. Graves,

The Underground Injection Control Program of the Wyoming Department of Environmental Quality, Water Quality Division (UIC Program), has been informed from multiple sources that the septic system for this facility serves at least 12 households. Average water disposal per household is generally accepted to be 350 gallons per day, which means that the septic system for the Crossed Arrows Subdivision accepts, at a minimum, 4,200 gallons per day of domestic waste. According to *Wyoming Water Quality Rules and Regulations, Chapter 16, Appendix A*, this facility qualifies as a 5E3 Domestic Subsurface Fluid Distribution System. The UIC Program hereby requires the Crossed Arrows Subdivision to initiate permit coverage through the UIC Program by completing and submitting a technically adequate individual permit application. If you would like to download an electronic version of this application, you can do so at the following website: <http://deq.state.wy.us/wqd/groundwater/uicprogram/index.asp>, once you reach this webpage, please scroll down the page to the "Class V Well Permit Application" link, clicking on this link will take you to the download screen. If you need assistance with this application, please contact any of the following:

Kathy Shreve
307-777-6682
kathy.shreve@wyo.gov

Carol McAdams
307-777-2960
carol.mcadams@wyo.gov

Nicole Twing
307-777-8275
nicole.twing@wyo.gov

Please note that operating a Class V injection well (which includes septic systems that accept more than 2,000 gallons per day of domestic waste) is a violation of *Wyoming Water Quality Rules and Regulations*. Violation of these regulations can incur enforcement actions, which can include fines and penalties.




The UIC Program has been notified by multiple sources that the septic system (leachfield) for the Crossed Arrows subdivision has failed, and that sewage is flowing onto the surface at this facility. Please note that "the operation of any Class V septic system with liquid waste visible on the surface shall be considered a failure of the system and a violation of these regulations." according to *Wyoming Water Quality Rules and Regulations, Chapter 16, Section 9.j*. In order to rectify this situation and avoid further enforcement actions, Crossed Arrows Subdivision must accomplish the following:

1. Immediately cease discharge of domestic waste into the failed leachfield.
2. Discharge into this facility's septic tank may continue, provided that the septic tank is pumped as often as necessary to prevent the domestic sewage from overflowing the tank. In addition, the domestic sewage pumped from this facility's tank must be disposed of in an approved facility.
3. Remediate/replace the failed leachfield in accordance with *Wyoming Water Quality Rules and Regulations, Chapter 11, Section D*. According to information on file with various other agencies, it appears that this facility's leachfield has had multiple failures since 1991, strongly indicating the need for leachfield replacement, likely by a different system than exists now.
4. Notify the Region 8 office of the EPA regarding this facility's leachfield failure, and conduct immediate water supply well testing to eliminate the possibility that the water supply for the Crossed Arrows subdivision has been contaminated.

Please remain in touch with the UIC Program regarding the accomplishment of each of the steps outlined below. Please note that failure to complete these steps in a timely manner may result in enforcement actions being taken against this facility.

If you have any questions, please contact me at the phone number or e-mail given above.

Sincerely,



Kathy Shreve

Environmental Program Principal
Wyoming Department of Environmental Quality
Water Quality Division
Underground Injection Control Program

KS/rm/12-0664



Department of Environmental Quality

To protect, conserve and enhance the quality of Wyoming's environment for the benefit of current and future generations.



Matthew H. Mead, Governor

John Corra, Director

July 23, 2012

CERTIFIED

David & Mary Flores
Crossed Arrows Subdivision
P.O. Box 93
Meeteetse, WY 82433

RE: SURFACING SEPTIC SYSTEM EFFLUENT, SUBMISSION OF UNDERGROUND INJECTION CONTROL PERMIT FOR CROSSED ARROWS SUBDIVISION'S SEPTIC SYSTEM

Dear Mr. & Mrs. Flores,

The Underground Injection Control Program of the Wyoming Department of Environmental Quality, Water Quality Division (UIC Program), has been informed from multiple sources that the septic system for this facility serves at least 12 households. Average water disposal per household is generally accepted to be 350 gallons per day, which means that the septic system for the Crossed Arrows Subdivision accepts, at a minimum, 4,200 gallons per day of domestic waste. According to *Wyoming Water Quality Rules and Regulations, Chapter 16, Appendix A*, this facility qualifies as a 5E3 Domestic Subsurface Fluid Distribution System. The UIC Program hereby requires the Crossed Arrows Subdivision to initiate permit coverage through the UIC Program by completing and submitting a technically adequate individual permit application. If you would like to download an electronic version of this application, you can do so at the following website: <http://deq.state.wy.us/wqd/groundwater/uicprogram/index.asp>, once you reach this webpage, please scroll down the page to the "Class V Well Permit Application" link, clicking on this link will take you to the download screen. If you need assistance with this application, please contact any of the following:

Kathy Shreve
307-777-6682
kathy.shreve@wyo.gov

Carol McAdams
307-777-2960
carol.mcadams@wyo.gov

Nicole Twing
307-777-8275
nicole.twing@wyo.gov

Please note that operating a Class V injection well (which includes septic systems that accept more than 2,000 gallons per day of domestic waste) is a violation of *Wyoming Water Quality Rules and Regulations*. Violation of these regulations can incur enforcement actions, which can include fines and penalties.



The UIC Program has been notified by multiple sources that the septic system (leachfield) for the Crossed Arrows subdivision has failed, and that sewage is flowing onto the surface at this facility. Please note that "the operation of any Class V septic system with liquid waste visible on the surface shall be considered a failure of the system and a violation of these regulations." according to *Wyoming Water Quality Rules and Regulations, Chapter 16, Section 9.j*. In order to rectify this situation and avoid further enforcement actions, Crossed Arrows Subdivision must accomplish the following:

1. Immediately cease discharge of domestic waste into the failed leachfield.
2. Discharge into this facility's septic tank may continue, provided that the septic tank is pumped as often as necessary to prevent the domestic sewage from overflowing the tank. In addition, the domestic sewage pumped from this facility's tank must be disposed of in an approved facility.
3. Remediate/replace the failed leachfield in accordance with *Wyoming Water Quality Rules and Regulations, Chapter 11, Section D*. According to information on file with various other agencies, it appears that this facility's leachfield has had multiple failures since 1991, strongly indicating the need for leachfield replacement, likely by a different system than exists now.
4. Notify the Region 8 office of the EPA regarding this facility's leachfield failure, and conduct immediate water supply well testing to eliminate the possibility that the water supply for the Crossed Arrows subdivision has been contaminated.

Please remain in touch with the UIC Program regarding the accomplishment of each of the steps outlined below. Please note that failure to complete these steps in a timely manner may result in enforcement actions being taken against this facility.

If you have any questions, please contact me at the phone number or e-mail given above.

Sincerely,



Kathy Shreve
Environmental Program Principal
Wyoming Department of Environmental Quality
Water Quality Division
Underground Injection Control Program

KS/rm/12-0665



Department of Environmental Quality

To protect, conserve and enhance the quality of Wyoming's environment for the benefit of current and future generations.



Matthew H. Mead, Governor

John Corra, Director

July 23, 2012

CERTIFIED

Gary & Debra Grotegut
Crossed Arrows Subdivision
1579 Acorn Road
Waukon, IA 52172

RE: SURFACING SEPTIC SYSTEM EFFLUENT, SUBMISSION OF UNDERGROUND INJECTION CONTROL PERMIT FOR CROSSED ARROWS SUBDIVISION'S SEPTIC SYSTEM

Dear Mr. & Mrs. Grotegut,

The Underground Injection Control Program of the Wyoming Department of Environmental Quality, Water Quality Division (UIC Program), has been informed from multiple sources that the septic system for this facility serves at least 12 households. Average water disposal per household is generally accepted to be 350 gallons per day, which means that the septic system for the Crossed Arrows Subdivision accepts, at a minimum, 4,200 gallons per day of domestic waste. According to *Wyoming Water Quality Rules and Regulations, Chapter 16, Appendix A*, this facility qualifies as a 5E3 Domestic Subsurface Fluid Distribution System. The UIC Program hereby requires the Crossed Arrows Subdivision to initiate permit coverage through the UIC Program by completing and submitting a technically adequate individual permit application. If you would like to download an electronic version of this application, you can do so at the following website: <http://deq.state.wy.us/wqd/groundwater/uicprogram/index.asp>, once you reach this webpage, please scroll down the page to the "Class V Well Permit Application" link, clicking on this link will take you to the download screen. If you need assistance with this application, please contact any of the following:

Kathy Shreve
307-777-6682
kathy.shreve@wyo.gov

Carol McAdams
307-777-2960
carol.mcadams@wyo.gov

Nicole Twing
307-777-8275
nicole.twing@wyo.gov

Please note that operating a Class V injection well (which includes septic systems that accept more than 2,000 gallons per day of domestic waste) is a violation of *Wyoming Water Quality Rules and Regulations*. Violation of these regulations can incur enforcement actions, which can include fines and penalties.




The UIC Program has been notified by multiple sources that the septic system (leachfield) for the Crossed Arrows subdivision has failed, and that sewage is flowing onto the surface at this facility. Please note that "the operation of any Class V septic system with liquid waste visible on the surface shall be considered a failure of the system and a violation of these regulations." according to *Wyoming Water Quality Rules and Regulations, Chapter 16, Section 9.j*. In order to rectify this situation and avoid further enforcement actions, Crossed Arrows Subdivision must accomplish the following:

1. Immediately cease discharge of domestic waste into the failed leachfield.
2. Discharge into this facility's septic tank may continue, provided that the septic tank is pumped as often as necessary to prevent the domestic sewage from overflowing the tank. In addition, the domestic sewage pumped from this facility's tank must be disposed of in an approved facility.
3. Remediate/replace the failed leachfield in accordance with *Wyoming Water Quality Rules and Regulations, Chapter 11, Section D*. According to information on file with various other agencies, it appears that this facility's leachfield has had multiple failures since 1991, strongly indicating the need for leachfield replacement, likely by a different system than exists now.
4. Notify the Region 8 office of the EPA regarding this facility's leachfield failure, and conduct immediate water supply well testing to eliminate the possibility that the water supply for the Crossed Arrows subdivision has been contaminated.

Please remain in touch with the UIC Program regarding the accomplishment of each of the steps outlined below. Please note that failure to complete these steps in a timely manner may result in enforcement actions being taken against this facility.

If you have any questions, please contact me at the phone number or e-mail given above.

Sincerely,



Kathy Shreve
Environmental Program Principal
Wyoming Department of Environmental Quality
Water Quality Division
Underground Injection Control Program

KS/rm/12-0666



Department of Environmental Quality

To protect, conserve and enhance the quality of Wyoming's environment for the benefit of current and future generations.



Matthew H. Mead, Governor

John Corra, Director

July 23, 2012

CERTIFIED

Clinton & Yalanda Fewell
Crossed Arrows Subdivision
1036 Warden Street
Fort Worth, TX 76126-2506

RE: SURFACING SEPTIC SYSTEM EFFLUENT, SUBMISSION OF UNDERGROUND INJECTION CONTROL PERMIT FOR CROSSED ARROWS SUBDIVISION'S SEPTIC SYSTEM

Dear Mr. & Mrs. Fewell,

The Underground Injection Control Program of the Wyoming Department of Environmental Quality, Water Quality Division (UIC Program), has been informed from multiple sources that the septic system for this facility serves at least 12 households. Average water disposal per household is generally accepted to be 350 gallons per day, which means that the septic system for the Crossed Arrows Subdivision accepts, at a minimum, 4,200 gallons per day of domestic waste. According to *Wyoming Water Quality Rules and Regulations, Chapter 16, Appendix A*, this facility qualifies as a 5E3 Domestic Subsurface Fluid Distribution System. The UIC Program hereby requires the Crossed Arrows Subdivision to initiate permit coverage through the UIC Program by completing and submitting a technically adequate individual permit application. If you would like to download an electronic version of this application, you can do so at the following website: <http://deq.state.wy.us/wqd/groundwater/uicprogram/index.asp>, once you reach this webpage, please scroll down the page to the "Class V Well Permit Application" link, clicking on this link will take you to the download screen. If you need assistance with this application, please contact any of the following:

Kathy Shreve
307-777-6682
kathy.shreve@wyo.gov

Carol McAdams
307-777-2960
carol.mcadams@wyo.gov

Nicole Twing
307-777-8275
nicole.twing@wyo.gov

Please note that operating a Class V injection well (which includes septic systems that accept more than 2,000 gallons per day of domestic waste) is a violation of *Wyoming Water Quality Rules and Regulations*. Violation of these regulations can incur enforcement actions, which can include fines and penalties.




The UIC Program has been notified by multiple sources that the septic system (leachfield) for the Crossed Arrows subdivision has failed, and that sewage is flowing onto the surface at this facility. Please note that "the operation of any Class V septic system with liquid waste visible on the surface shall be considered a failure of the system and a violation of these regulations." according to *Wyoming Water Quality Rules and Regulations, Chapter 16, Section 9.j*. In order to rectify this situation and avoid further enforcement actions, Crossed Arrows Subdivision must accomplish the following:

1. Immediately cease discharge of domestic waste into the failed leachfield.
2. Discharge into this facility's septic tank may continue, provided that the septic tank is pumped as often as necessary to prevent the domestic sewage from overflowing the tank. In addition, the domestic sewage pumped from this facility's tank must be disposed of in an approved facility.
3. Remediate/replace the failed leachfield in accordance with *Wyoming Water Quality Rules and Regulations, Chapter 11, Section D*. According to information on file with various other agencies, it appears that this facility's leachfield has had multiple failures since 1991, strongly indicating the need for leachfield replacement, likely by a different system than exists now.
4. Notify the Region 8 office of the EPA regarding this facility's leachfield failure, and conduct immediate water supply well testing to eliminate the possibility that the water supply for the Crossed Arrows subdivision has been contaminated.

Please remain in touch with the UIC Program regarding the accomplishment of each of the steps outlined below. Please note that failure to complete these steps in a timely manner may result in enforcement actions being taken against this facility.

If you have any questions, please contact me at the phone number or e-mail given above.

Sincerely,




Kathy Shreve
Environmental Program Principal
Wyoming Department of Environmental Quality
Water Quality Division
Underground Injection Control Program

KS/rm/12-0667



Department of Environmental Quality

To protect, conserve and enhance the quality of Wyoming's environment for the benefit of current and future generations.



Matthew H. Mead, Governor

John Corra, Director

July 23, 2012

CERTIFIED

Paul & Joie Fowler
Crossed Arrows Subdivision
c/o Garret Alksnitis
P.O. Box 296
Meeteetse, WY 82433

RE: SURFACING SEPTIC SYSTEM EFFLUENT, SUBMISSION OF UNDERGROUND INJECTION CONTROL PERMIT FOR CROSSED ARROWS SUBDIVISION'S SEPTIC SYSTEM

Dear Mr. & Mrs. Fowler,

The Underground Injection Control Program of the Wyoming Department of Environmental Quality, Water Quality Division (UIC Program), has been informed from multiple sources that the septic system for this facility serves at least 12 households. Average water disposal per household is generally accepted to be 350 gallons per day, which means that the septic system for the Crossed Arrows Subdivision accepts, at a minimum, 4,200 gallons per day of domestic waste. According to *Wyoming Water Quality Rules and Regulations, Chapter 16, Appendix A*, this facility qualifies as a 5E3 Domestic Subsurface Fluid Distribution System. The UIC Program hereby requires the Crossed Arrows Subdivision to initiate permit coverage through the UIC Program by completing and submitting a technically adequate individual permit application. If you would like to download an electronic version of this application, you can do so at the following website: <http://deq.state.wy.us/wqd/groundwater/uicprogram/index.asp>, once you reach this webpage, please scroll down the page to the "Class V Well Permit Application" link, clicking on this link will take you to the download screen. If you need assistance with this application, please contact any of the following:

Kathy Shreve
307-777-6682
kathy.shreve@wyo.gov

Carol McAdams
307-777-2960
carol.mcadams@wyo.gov

Nicole Twing
307-777-8275
nicole.twing@wyo.gov

Please note that operating a Class V injection well (which includes septic systems that accept more than 2,000 gallons per day of domestic waste) is a violation of *Wyoming Water Quality Rules and Regulations*. Violation of these regulations can incur enforcement actions, which can include fines and penalties.



The UIC Program has been notified by multiple sources that the septic system (leachfield) for the Crossed Arrows subdivision has failed, and that sewage is flowing onto the surface at this facility. Please note that "the operation of any Class V septic system with liquid waste visible on the surface shall be considered a failure of the system and a violation of these regulations." according to *Wyoming Water Quality Rules and Regulations, Chapter 16, Section 9.j*. In order to rectify this situation and avoid further enforcement actions, Crossed Arrows Subdivision must accomplish the following:

1. Immediately cease discharge of domestic waste into the failed leachfield.
2. Discharge into this facility's septic tank may continue, provided that the septic tank is pumped as often as necessary to prevent the domestic sewage from overflowing the tank. In addition, the domestic sewage pumped from this facility's tank must be disposed of in an approved facility.
3. Remediate/replace the failed leachfield in accordance with *Wyoming Water Quality Rules and Regulations, Chapter 11, Section D*. According to information on file with various other agencies, it appears that this facility's leachfield has had multiple failures since 1991, strongly indicating the need for leachfield replacement, likely by a different system than exists now.
4. Notify the Region 8 office of the EPA regarding this facility's leachfield failure, and conduct immediate water supply well testing to eliminate the possibility that the water supply for the Crossed Arrows subdivision has been contaminated.

Please remain in touch with the UIC Program regarding the accomplishment of each of the steps outlined below. Please note that failure to complete these steps in a timely manner may result in enforcement actions being taken against this facility.

If you have any questions, please contact me at the phone number or e-mail given above.

Sincerely,



Kathy Shreve
Environmental Program Principal
Wyoming Department of Environmental Quality
Water Quality Division
Underground Injection Control Program

KS/rm/12-0668



Department of Environmental Quality

To protect, conserve and enhance the quality of Wyoming's environment for the benefit of current and future generations.



Matthew H. Mead, Governor

John Corra, Director

July 25, 2012

CERTIFIED

BBCA-WaterBoard
Big Valley - Crossed Arrows Subdivision
P.O. Box 33
Meeteetse, WY 82433

RE: SURFACING SEPTIC SYSTEM EFFLUENT, SUBMISSION OF UNDERGROUND INJECTION CONTROL PERMIT FOR CROSSED ARROWS SUBDIVISION'S SEPTIC SYSTEM

Dear Jerry Justice
Steve Skinner
Wayne McBroom

The Underground Injection Control Program of the Wyoming Department of Environmental Quality, Water Quality Division (UIC Program), has been informed from multiple sources that the septic system for this facility serves at least 12 households. Average water disposal per household is generally accepted to be 350 gallons per day, which means that the septic system for the Crossed Arrows Subdivision accepts, at a minimum, 4,200 gallons per day of domestic waste. According to *Wyoming Water Quality Rules and Regulations, Chapter 16, Appendix A*, this facility qualifies as a 5E3 Domestic Subsurface Fluid Distribution System. The UIC Program hereby requires the Crossed Arrows Subdivision to initiate permit coverage through the UIC Program by completing and submitting a technically adequate individual permit application. If you would like to download an electronic version of this application, you can do so at the following website: <http://deq.state.wy.us/wqd/groundwater/uicprogram/index.asp>, once you reach this webpage, please scroll down the page to the "Class V Well Permit Application" link, clicking on this link will take you to the download screen. If you need assistance with this application, please contact any of the following:

Kathy Shreve
307-777-6682
kathy.shreve@wyo.gov

Carol McAdams
307-777-2960
carol.mcadams@wyo.gov

Nicole Twing
307-777-8275
nicole.twing@wyo.gov

Please note that operating a Class V injection well (which includes septic systems that accept more than 2,000 gallons per day of domestic waste) is a violation of *Wyoming Water Quality Rules and Regulations*. Violation of these regulations can incur enforcement actions, which can include fines and penalties.




The UIC Program has been notified by multiple sources that the septic system (leachfield) for the Crossed Arrows subdivision has failed, and that sewage is flowing onto the surface at this facility. Please note that "the operation of any Class V septic system with liquid waste visible on the surface shall be considered a failure of the system and a violation of these regulations." according to *Wyoming Water Quality Rules and Regulations, Chapter 16, Section 9.j*. In order to rectify this situation and avoid further enforcement actions, Crossed Arrows Subdivision must accomplish the following:

1. Immediately cease discharge of domestic waste into the failed leachfield.
2. Discharge into this facility's septic tank may continue, provided that the septic tank is pumped as often as necessary to prevent the domestic sewage from overflowing the tank. In addition, the domestic sewage pumped from this facility's tank must be disposed of in an approved facility.
3. Remediate/replace the failed leachfield in accordance with *Wyoming Water Quality Rules and Regulations, Chapter 11, Section D*. According to information on file with various other agencies, it appears that this facility's leachfield has had multiple failures since 1991, strongly indicating the need for leachfield replacement, likely by a different system than exists now.
4. Notify the Region 8 office of the EPA regarding this facility's leachfield failure, and conduct immediate water supply well testing to eliminate the possibility that the water supply for the Crossed Arrows subdivision has been contaminated.

Please remain in touch with the UIC Program regarding the accomplishment of each of the steps outlined below. Please note that failure to complete these steps in a timely manner may result in enforcement actions being taken against this facility.

If you have any questions, please contact me at the phone number or e-mail given above.

Sincerely,



Kathy Shreve
Environmental Program Principal
Wyoming Department of Environmental Quality
Water Quality Division
Underground Injection Control Program

KS/rm/12-0676