

**LIMITED MINE OPERATION (LMO)
INSPECTION REPORT**

Wyoming Department of Environmental Quality, Land Quality Division
200 West 17th Street, Suite 10, Cheyenne, WY 82002
(307) 777-7756 FAX: (307) 635-1784



LMO Number:	ET1496	Operator:	QUALITY LANDSCAPE & NURSERY INC
Inspection Date:	9/27/2022	Inspector(s):	Brian Goodnough
Report Date:	11/1/2022	Participant(s):	Randy Stevens (Quality Landscape)
Last Inspection:	8/9/2022	Reclamation Estimate:	\$66,000
Inspection Reason(s):	Follow-up	Field Conditions:	Sunny, 72°F @ 11:28 am
Status:	Inactive	Approved Acreage:	1
County:	Carbon	Mineral:	Sand & Gravel
Total Disturbed Acres:	1		

Opening Comments

Authorization of the Limited Mining Operation (LMO) was issued to Quality Landscape & Nursery, Inc. (Quality Landscape) on July 22, 2010. The LMO is located in Lots 1 thru 11, Block 1 (NE1/4NE1/4 of Section 14 T17N R84W) within the Town of Saratoga, Wyoming.

Quality Landscape signed the Settlement Agreement (SA) for the Notice of Violation (NOV) Docket No. 5970-19 on July 29, 2022. The executed SA for NOV Docket No. 5970-19 specifies under Item 7.a. that Quality Landscape will restrict public access to areas that pose public health and danger with fencing. In addition, Item 7.b. specifies that Quality Landscape must post warning signs on the perimeter of the LMO ET1496 area and on all fencing to identify the potential danger. On August 9, 2022, Land Quality Division (LQD) conducted a site inspection and noted that the required fencing and warning signs had been removed from the site. LQD followed up with a phone call to Quality Landscape with instructions to reinstall the fencing and warning signs or a violation would be issued for not meeting the requirements of the executed SA. LQD conducted this inspection to verify the fencing and warning signs were reinstalled around the sheet pile wall. At the time of this inspection, the fencing was reinstalled and warning signs were posted around areas that pose public health and danger (**Photo #1**).

Inspection Summary Comments

Quality Landscape will continue to maintain the fencing and warning signs in the areas that pose a public health danger. LQD will issue a notice of violation for the removal of these structures or signage from these areas.

Inspection Recipient and Attachment Information

Recipient	Email	Address/Notes
Operator	Yes	Randy Stevens, randyqln@union-tel.com
Wyoming Attorney General's Office	Yes	David Dewald, david.dewalt@wyo.gov
Wyoming State Mine Inspector's Office	Yes	Heather Kroupa, heather.kroupa@wyo.gov

Attachment Types: Photo Addendum Map(s) Table(s) Other

Attachment Notes

Type	FileName	Size (MB)	# Pages
Photos	2022-09-27-ET1496-IR-Photos.pdf	0.17	1

ANNUAL INSPECTION REPORT
QUALITY LANDSCAPE & NURSEY, INC.
LIMITED MINING OPERATION ET1496

PHOTO ADDENDUM



Photo #1: Quality Landscape reinstated the fencing and warning signs around the sheet pile wall.